

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7





FIG. 8



(B)

unit:mm

	DIMENSION B	DEMENSION C	DIMENSION (B-A)/2
COUNTERWEIGHT	$\phi 6$	1.5	
5500rpm	$\phi 6$	1.5	1.25
8000rpm	$\phi 6.1$	1.5	1.8